



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

September 05, 2007

Supervisor

*DOZ*

**Mine Name:** Trace Mine #1

**Operator Name:** Peak Minerals-Azomite Inc.

**Permit number:** M/039/001

**Inspection Date:** August 27, 2007

**Time:** 12:30 pm

**Inspector(s):** Lynn Kunzler, DOGM

**Other Participants:** none

**Mine Status:** Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area.

#### Inspection Summary:

There was no activity at this site during this inspection, however the site is considered active. The only significant change noted since my last inspection was the stockpiled material has been removed from the site.

Vegetation establishment on the area that had been reclaimed is progressing. While no data was collected, it visually appears to be close to meeting revegetation standards.

There were no erosion problems, litter, or deleterious materials noted on site. The mine site is fenced to keep the public out, and the gate was locked.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Continue to monitor this site when in the area.

**Inspector's Signature**

*[Signature]*

LK:pb

O:\M039-Sanpete\S0390001-TraceMine\Inspections\Insp-08272007.doc